


## Figures






FIG. 2





FIG. 3



SENSOR OUTPUT  
AFFECTED BY SUBWOOFER

FIG. 4